steinel

Slave/wireless master interconnection circuit diagram